37502

Xerox® VersaLink® B625 Multifunction Printer

xerox™

Repeating Defects



Imaging Unit

Transfer Roller

Fuser

To identify the component causing the defect, compare your print sample against the measurements shown.

To diagnose a defect on the transfer belt, print eight Letter/A4-size pages. Verify that the same defect appears on every fourth page.

Call for service for this defect.

© 2022 Xerox Corporation. All Rights Reserved. Xerox® and VersaLink® are trademarks of Xerox Corporation in the United States and/or other countries. BR34561

www.xerox.com/office/support